1886744
O- Barley Twist Plant Pedestal

Parts List

A.	Top Panel	1 pc
B.	Spindle	1 pc
C.	Bottom Panel	1 pc

* Please make sure that you have all the parts indicated before you begin assembly of this item.
* This item should be assembled on a soft surface to prevent scratching the finish during assembly.
* This item may require periodic tightening.

1. Place Top Panel (A) upside down on a soft surface. Align the exposed thread on Spindle (B) with the pre-threaded hole on the underside of Top Panel (A) and securely tighten by turning in a clockwise direction. Align the pre-threaded hole on Bottom Panel (C) with the exposed thread on Spindle (B) and securely tighten by turning in a clockwise direction. See illustration.